



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

export@sirsafety.com  
www.sirsafety.com



UNI EN ISO 9001:2015  
UNI EN ISO 14001:2015  
UNI EN ISO 45001:2018

<b>Name: FUSION STRETCH trousers</b>	<b>Code: MC1716QJ</b>	<b>MC17 CLOTHING - FUSION SERIES</b>
--------------------------------------	-----------------------	--------------------------------------

**Description**

Trousers in twill 97% cotton and 3% spandex, 240 g/m  
Featuring zip and stud button closure, two front pockets with fifth pocket on the right, right pocket ruler pocket and hammer loop, right rear pocket closed with flap and Velcro.  
Rear left pocket closed with Velcro, multifunctional utility pocket with flap and velcro, with pen and mobile phone holder, oversized belt loops, reinforcement bar tacks in contrasting colour, double stitched seams.

The Fusion series is:

- made of a strong fabric, suitable to the most demanding jobs;
- resistant, practical and functional and features a wide range of accessories, multifunctional utility pockets and wear resistant reinforcements in technical fabric;
- equipped with details such as the reinforced runners and jointed double seams in contrasting colour, which assure long-lasting use and high quality.

Protection against risks of dirt and detrimental actions of slight damage  
The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.



certified



Category <b>I</b>	Colours NAVY/GREY	Available Sizes Made to order: 38 - 38, 60 - 70 In stock: 46 - 58
Quantity/Carton <b>20</b>	EC Standards EN ISO 13688	Important Information Suitable for: Mechanical Engineering, Construction, Goods Handling, Transport, Agriculture and Maintenance. Store in a cool, dry place, away from heat sources and away from light. Before each use, carry out a visual check to ensure that the device is in perfect condition, undamaged and clean, and replace it if it is not intact. Follow the recommended washing instructions.
Dexterity		Storage and cleaning